

**star bulletin****Service Campaigns**

Date: October 2005
Campaign No. 2005090017
Supersedes:
Group: 77

Revision:

SUBJECT: MODEL 203.7 MODEL YEAR 2004
Replace wind deflector linkage for panoramic roof

This Service Campaign has been initiated because DCAG has determined that on the affected vehicles (see VIN range below) the wind deflector linkage may not perform properly on rough roads in high temperatures. Dealers will replace the wind deflector linkage with an updated part.

Prior to performing this Service Campaign:

- Please check VMI to insure the vehicle is involved and to determine if the vehicle has been previously repaired.
- Please review the entire Service Campaign bulletin.

Approximately 216 vehicles are affected.

Effective Serial Number Range

Model	Chassis End Number	
	From	To
203.740	F472725	F473568
203.764	F472859	F475077

Note:

Every vehicle in the VIN range may not be included in the campaign. VMI must always be checked before performing

campaigns to verify that the campaign is required on a specific vehicle. VMI **always** overrides the bulletin in reference to a specific vehicle's inclusion in a particular campaign. Please also note that Recall and Service Campaigns **do not expire** and may also be performed on a vehicle with a vehicle status indicator.




Figure 1

- 1. Open panoramic roof.
- 2. Remove e-clip (5, Figure 1).
- 3. Remove bolt (1, Figure 1).
- 4. Remove screw (4, Figure 1) from linkage (3).

Note:
Linkage is under spring tension.

- 5. Move linkage (3, Figure 1) toward front of vehicle.
- 6. Remove linkage (3, Figure 1) from wind deflector (2).
- 7. Install new linkage in reverse order.

Note:
Re-Install bolt with bolt head toward center of vehicle and groove toward the outside.

- 8. Repeat procedure on opposite side.

Primary Parts Information

Qty.	Part Name	Part Number	Estimated Replacement Rate
1	Left linkage	A 203 780 01 75	100%

1	Right linkage	A 203 780 02 75	100%
---	---------------	-----------------	------

Note: There are no Secondary Parts for this Campaign.

Note:

- Please be aware that only the part number(s) referenced in the Campaign Bulletin is/are approved for use to repair the vehicle. Repairs performed using any other part(s) will not have been performed in accordance with the campaign. Accordingly, warranty claims submitted with reference to an improper part number(s) will be denied.
- The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information			
Operation: Wind deflector linkage, replace (02-4093)			
Damage Code	Operation Number	Time (hrs.)	Model Indicator (s)
78 910 33 7	02-4093	0.4 hrs..	Q1, Q4